

Appendix C1

South Tyneside Council

RISK ASSESSMENT

Department: Services for Young People, Children, Adults & Families			Section: Thurston	Section: Thurston O.E.C.					
Work Activity	Tractor								
Hazards	Vehicle. Fit for pu Other site users. Mechanical failure	•	Excessive/unbalanced load Weather / Ground conditions			Risk rating, without controls (see Matrix overleaf)			
	Hydraulic equipme Log splitter	ent	Driver ability Refuelling	High					
	Fire Lone working			Medium					
	Unauthorised use Changing of attachments								
Population Exposed	Employees:	\square	Sub Contractors:	tors: 🛛 Pub		lic:			
	Young Persons:	\square	Special Groups:	oups: 🛛 Chi					
Measures	Regular maintenance and scheduled vehicle checks Consideration given to when and how tractor is used Lone working only when appropriate Ensure tractor is locked and secured after use Log splitter only to be used by trained personnel Whenever possible use left hand door Consideration give to locking off hydraulic bucket when not in use Manual handling and safety best practise to be followed when changing attachments and refuelling Continue on separate sheet, if necessary								
Information Instruction Training Required	Only to be used b	y officia	ally trained staff.						
Personal Protective Measures (PPE)									

Implementation Plan							Whom	Target Date		
_	with	Controls in p			HIGH	\square	MEDIUM			
Monitoring and Review		Review Date				By	Whom	Target Date		
		n 2022				Pre	14/1- 0-100	Jan 2023		
Action Identified From Review	INC	ne				Ву	Whom	Target Date		
	•			sk Ma						
		Worst Case Outcome					_			
	ð		Fatality		Major Inj	ury	Minor Injury	<u>/</u>		
	poq	Probable	HIGH	1	HIGH		MED.	_		
	Likelihood	Possible	HIGH		MED		MED.			
	_	Improbable	MED		LOW		LOW			
Assessment conducted by: Signed: Date: Revised: January 2022 AS, AD, JH, SB, JY. .										